


open bench, then complete steps A-C.



For item 1 a M10 Allen Key is required.

